Using the PRINT-command.

1) Close all "Marked Sets"-windows.
2) Open "Print Options".
3) Apply the check in "Printer", and leave everything else blank (no checkmarks anywhere else).
4) Click "OK".
   Now the global settings are in place. There will be print to printer, nowhere else!
5) Open the "Marked Sets"-window.
6) Choose the "Marked Sets", for which the setting shall be changed, by marking it with one click.
7) Open "Print Options".
8) Choose "Use Global Print Settings".
9) Click "OK".
10) Repeat step 6-9, for the rest of the "Marked Sets"-markings you might have.
11) Close the "Marked Sets"-window.
12) Open "Print Options".
13) Remove the check-mark in "Printer", so now NOTHING is marked in this window.
14) Click "OK".
    Now every print will be controlled from the program, meaning that the PRINT-command is taking over. Using this method will also be controlled be the markings made with <F3>.
    These 14 steps will make sure that YOU are in control of what will be printed and what not.
    Otherwise **NOTHING** will be printed/saved.