

## pc-dmis HOTKEY CHART

<b>Ctrl + Left Click</b>	Click on feature in the graphic window, will jump to feature in edit window.
<b>Ctrl + F1</b>	Translate mode.
<b>Ctrl + F2</b>	Rotate 2D (in graphics window) Toggle bookmarks (in edit).
<b>Ctrl + F3</b>	Rotate 3D.
<b>Ctrl + F4</b>	Program Mode.
<b>Ctrl + F5</b>	Curves and surfaces toggle.
<b>Ctrl + A</b>	Highlights all the text in the edit window.
<b>Ctrl + B</b>	Toggle breakpoint on/off.
<b>Ctrl + C</b>	Copies highlighted text to clipboard.
<b>Ctrl + D</b>	Deletes last feature, or feature that cursor is inside.
<b>Ctrl + E</b>	Executes last measured feature or feature with cursor in front of or inside.
<b>Ctrl + F</b>	Auto features dialog box.
<b>Ctrl + G</b>	Insert a read point.
<b>Ctrl + H</b>	Take a probe hit at current location.
<b>Ctrl + K</b>	Keeps most recently measured dimension.
<b>Ctrl + L</b>	Runs block of highlighted section of code (Ctrl + E does this also)
<b>Ctrl + N</b>	Displays new part program dialog box.
<b>Ctrl + M</b>	Inserts a move point.
<b>Ctrl + O</b>	Displays the open file dialog box.
<b>Ctrl + P</b>	Displays the print dialog box.
<b>Ctrl + Q</b>	Executes from the beginning of the program.
<b>Ctrl + R</b>	Rotate box.
<b>Ctrl + T</b>	Master/Slave mode toggle.
<b>Ctrl + U</b>	Executes program from cursor.
<b>Ctrl + V</b>	Pastes clipboard.
<b>Ctrl + W</b>	Displays probe position dialog box.
<b>Ctrl + X</b>	Cuts highlighted text.
<b>Ctrl + Y</b>	Executes program from a specified location.
<b>Ctrl + Z</b>	Scale to fit (graphics window).
<b>Alt + -</b>	Deletes last hit.
<b>Alt + F3</b>	Displays edit window search box.
<b>Alt + Z</b>	DCC mode.
<b>Ctrl + Alt + A</b>	Displays the alignment utility box.
<b>Ctrl + Alt + P</b>	Displays the probe utility box.
<b>Ctrl + End</b>	Takes you to the end of the program.
<b>Ctrl + Home</b>	Takes you to the beginning of the program.
<b>F1</b>	Help.
<b>F2</b>	Displays the expression builder box.
<b>F3</b>	Mark/Unmark toggle.
<b>F4</b>	Prints the edit window.
<b>F5</b>	Displays the setup options dialog box.
<b>F6</b>	Displays the font selection box.
<b>F7</b>	Toggle fields.
<b>F8</b>	Toggle backward.
<b>F9</b>	Displays the feature dialog box.
<b>F10</b>	Displays the parameters options box.
<b>Shift + F3</b>	Will mark all.
<b>Shift + F10</b>	Displays the jump box.