

-File

↳ reporting

↳ template (label)

- open the template you use w/ clicker name
(ex. FILE-HEADER-TRACKER.LBL)

↳ click on template to show green boxes

↳ ~~double click~~ double click in stats number window →

make sure you highlight both boxes/cells for the
stats number - then right click

- merge cells

- make sure cell expression says =TRACEFIELD(1)

- change lines to thick on all sides

↳ ~~FILE~~ FILE SAVE, FILE CLOSE

- in your program use dropdown - insert - statistics

command-tracefield (OR TYPE in edit, command mode)

↳ Name: OPERATOR

↳ Value: NAME