

PCDMIS SHORTCUTS

CNTRL "E" – EXECUTES SINGLE FEATURES/COMMANDS

CNTRL "U" – EXECUTES FROM THE CURSOR TO THE END OF PROGRAM

CNTRL-ALT-"A" – NEW ALIGNMENT

CNTRL "S" – SAVES PROGRAM

CNTRL "M" – MOVEPOINT

CNTRL "A" – SELECT ALL

CNTRL "C" – COPY

CNTRL "X" – CUT

CNTRL "V" – PASTE

CNTRL "B" – BREAKPOINT (CLEAR BREAKPOINT)

"F3" – MARK / UNMARK

"F5" – SETUP

"F7" – TOGGLE

"F9" – OPENS FEATURES IN THE EDIT WINDOW

"F10" – PARAMETERS (Prehit/Retract, etc...)

ALT "F3" – FIND/SEARCH

ALT "-" – SUBTRACT A POINT