


Laying Flat on CMM.

Question:
How would E-F
G-H be created.
I have taken points
E, F, G, H, created
Generic perfect Basic ⌀
pierce points between
E-F line + Basic ⌀
G-H line + Basic ⌀
Created line with
pierce points, reported
lines \cap , but getting
.297, way out.



E ↔ F
G ↔ H