


Run Chart - ID_CIRCLE_1.302.D

NOM  SL  CL

D= Diameter




to zoom, Shift & Left Button to pan, Shift & Double-click to reset.

Run Chart - ID_CIRCLE_1.302.RN



NOM  CL 

R= Roundness




Shift & Wheel to zoom, Shift & Left Button to pan, Shift & Double-click to reset.

Run Chart - ID_CIRCLE_1.302.M

NOM  SL 

M= ?



to zoom, Shift & Left Button to pan, Shift & Double-click to reset.