

Often Used Symbols

Definition	Symbol	ASME Section
At Maximum Material Condition (MMC)	Ⓜ	3.3.5
At Least Material Condition (LMC)	Ⓛ	3.3.5
Diameter	∅	3.3.7
Between *	↔	3.3.11
Reference	()	3.3.8
Radius	R	3.3.7
Square	□	3.3.15
Centerline	Ⓢ	
Places or By	8X	